

KEY
1 Rake brick joints and flush repoint in NHL3.5 lime & sand mortar. Lithomex repairs to localised spalled brick. Remove vegetation from chimneypots. Provide galvanised cowls. Repair any cracks to concrete coping. New mortar flaunching. Survey lead flashing, repair or renew with Code 4 lead sheet.
2 Strip, clean and store ridge & hip tiles. Strip slates and check if sound. Remove exiting felt and provide breathable membrane on new treated battens. Re-slate with sound existing slates to east hip. Provide new natural slate to make up deficit. Use copper nails. Provide slate vents to rear. Re-bed ridge and hip tiles in lime mortar. Localised timber repairs if necessary. Refurbish historic RWG to west. Replace non-original RWG at front, east and rear with cast-iron units to match profile of original RWG
3 Remove cementitious render but leave decorative string-courses, opening surrounds and eaves corbels in situ. Provide lime render (Otterbein) to a ruled-and-lined finish. Scored lines to be refined. Make good any damaged string-courses or other decorative render elements. Like-for-like repairs to decorative render. Repaint surrounds.
4 Repair any cracking to cement-rendered surrounds. Renew surrounds where boast. Retain and refurbish timber sash windows. Retain glass. Provide new sash cords if required.
<b>5</b> For alterations, please refer to Architect's Drawings.
NOTES: ALL DIMENSIONS TO BE CHECKED ON SITE. DO NOT SCALE FROM DRAWING. DISCREPANCIES AND OMISSIONS TO BE REPORTED IMMEDIATELY TO CARRIG CONSERVATION INTERNATIONAL. THIS DRAWING IS COPYRIGHT AND IS ISSUED ON THE CONDITION THAT IT IS NOT COPIED EITHER WHOLLY OR IN PART WITHOUT THE CONSERVATION INTERNATIONAL
CARRRG conservation international
Second Floor - Atlantis Building South Cumberland Street phone: 09 333 1552980
e-mail: info@crarigie www.cerrigie cerving: Carr Cotter & Naessens Architects resert the Carlow Library resert the Rear Elevation reserts for Rear Elevation reserts for Rear Recommendations Drawings
Mit 10.12.2020 Kit 100@A3 R00   Image: 020024 R04 R04 R04 R04