



- KEY
- WASH COLOUR APPLIED OVER RENDER
 - RENDER PATCH REPAIR
 - CRACKS
 - RUST STAIN
 - ATMOSPHERIC STAINING
 - ORGANIC GREEN STAINING
 - FLAKING PAINTWORK TO RENDER
 - MISSING COURSE
 - BROKEN STRING COURSE TO ACCOMMODATE REPLACEMENT DOWNPIPE
 - VEGETATION TO CHIMNEY
 - FLAKING RENDER

FLAKING PAINT TO REPLACEMENT GUTTER

ATMOSPHERIC SOILING + LICHEN GROWTH TO STRING COURSE

ATMOSPHERIC SOILING + LICHEN GROWTH TO STRING COURSE

NOTES:
 ALL DIMENSIONS TO BE CHECKED ON SITE.
 DO NOT SCALE FROM DRAWING.
 DISCREPANCIES AND OMISSIONS TO BE REPORTED IMMEDIATELY TO CARRIG CONSERVATION INTERNATIONAL.
 THIS DRAWING IS COPYRIGHT AND IS ISSUED ON THE CONDITION THAT IT IS NOT COPIED EITHER WHOLLY OR IN PART WITHOUT THE CONSENT IN WRITING OF CARRIG CONSERVATION INTERNATIONAL

GENERAL NOTES:
 FLAKING AND WORN PAINTWORK TO ALL SASHES.
 FLAKING PAINT TO TIMBER DOORS.

CARRIG
 conservation international

Second Floor - Atlantis Building
 South Cumberland Street
 phone: 01 353 1 5529188
 e-mail: info@carrig.ie
 www.carrig.ie
 DRAWING COPYRIGHT - CARRIG CONSERVATION INTERNATIONAL

CLIENT
 Carr Cotter & Naessens Architects

PROJECT TITLE
 Carlow Library

DRAWING TITLE
 Front Elevation

DRAWING STATUS
 External Condition Drawings

DRAWN PT	DATE 24.07.2020	BY SH	SCALE 1:100@A3	PASS	REVISION NO. R00
PROJECT NUMBER 020024	DRAWING NUMBER C03				

FRONT ELEVATION, 1:100