

<u>KEY</u>

RENDER PATCH REPAIR

ATMOSPHERIC STAINING

CHANFERED BOTTOM CORNER OF SILL TO ACCOMODATE FORMER PITCH OF ROOF

FLAKING PAINTWORK TO RENDER

TES:

ALL DIMENSIONS TO BE CHECKED ON SITE.

DO NOT SCALE FROM DRAWING.

DISCREPANCIES AND OMISSIONS TO BE REPORTED IMMEDIATELY TO CARRIG CONSERVATION INTERNATIONAL.

THIS DRAWING IS COPYRIGHT AND IS ISSUED ON THE CONDITION THAT IT IS NOT COPIED EITHER WHOLLY OR IN PART WITHOUT THE CONSENT IN WRITING OF CARRIG CONSERVATION INTERNATIONAL



Second Floor – Atlantis Building
South Cumberland Street
phone: 00 353 1552980

e-mail: info@carrigie
www.carrigie
seawing.copysout-caneg.copysoutheantenant

Carr Cotter & Naessens Architects

Carlow Library

Rear Elevation

External Condition Drawings

| MAN | PT | SH | M45 | M15 |